

Notice concerning the use of Drive Xpert function

Due to vendor driver limitation, the use of Hitachi SATA HDDs is not supported by the two built-in Drive Xpert ports (orange x2 or orange x1 + white x1) at present stage, which may result in no detection of such HDDs.

Please avoid the use of such HDDs if intended to connect them to Driver Xpert ports.

Note1: This limitation does not affect other SATA ports.

Note2: The support for such HDDs will be implemented in the future driver releases.

DriverXpert機能について

Drive Xpert機能においてHitachiGST製ハードディスクをご利用頂く場合、一部型番のハードディスクではディスクを認識せず、利用出来ない場合があります。

将来的には、BIOS・Driver側で、HitachiGST製ハードディスクへの対応作業を行うことで互換性の問題を解消する予定ではございますが、現時点ではDrive Xpert機能の制限とさせていただきます。

Drive Xpertをご利用頂く場合には他社のハードディスクでの利用をお勧め致します。

なお、他のSATAコネクタにこうした制限はございません。