

Software Release Note

2005/7/31

Introduction: This document describes detailed release information containing firmware version, improvements, known issues and default configuration, etc.

1. Product Information

Model Name: AAM6020BI-T4, AAM6030BI

2. Version Information

Firmware Version: Turkey_4PORT_3.6.0C_1S00

DSL Version: 3.02.06.00

Driver Version: N/A

3. File Release Information

File Name:

Turkey_WLAN_3.6.0C_1S00.firmware.upgrade.img

4. Updates

New Features: N/A

Enhancements: N/A

Resolved Bugs:

1. Modify Wizard Static page "Mask" string
2. Change max PPP idle time to 10000 secs

5. Limitations

N/A

6. Known Issues

New Issues: N/A

Old Issues: N/A

Issued By		Reviewed By		Approved By		Rev
ASUS	2005/07/31					1.2

7. Default Configurations

Item		Default configurations
System Information	Login/Password	Admin/Admin
	Logo	ADSL Modem
	Language	English+Turkish
LAN Setting	LAN IP address/netmask	192.168.1.1/255.255.255.0
	DHCP Server (on/off)	On
	DHCP pool	192.168.1.2~254
ADSL Setting	Default mode (Multi, ANSI, G.dmt, G.lit)	Multi
WAN Setting	PVC setting	8/35(When create new connection)
	Protocol	PPPoE
	Encapsulation	LLC
Router Function	NAT (on/off)	On
	Firewall	On
Management	Telnet (LAN, WAN)	LAN
	HTTP (LAN, WAN)	LAN
	FTP (LAN, WAN)	LAN
Others	:	
	:	

8. Dependencies

Software Issues: N/A

Hardware Issues: N/A

- Compatible chipset: N/A
- Compatible PCB version: N/A

9. Note

N/A

Issued By		Reviewed By		Approved By		Rev
ASUS	2005/07/31					1.2