



---

This motherboard P5KPL-AM IN/ROEM/SI does not support the MB temperature monitoring function.

---