



Product: SiS Integrated 10/100 Fast Ethernet

Date: 10/24/2001

Document Type: Release Note

Driver Ver.: 1.14

Integrated LAN Driver [V1.14]

1. Windows98SE driver, WindowsMe driver, Winodws2000 driver, WindowsNT4.0 and WindowsXP driver certified by WHQL as for logo driver .

2. Submission ID is 532508.

3. To add 630ET support.

4. Support Netware 6.0

5.Bug fixed, Modification & Driver Version

[Windows XP]

a. Add 630ET support.

[Windows 2000]

a. Add 630ET support.

[Windows 98/98SE]

a. Add 630ET support.

[Windows Me]

a. Add 630ET support.

[Windows NT40]

a. Add 630ET support.

[Setup utility]

a. support driver installation under WindowsXP.

[Netware Client]

a. .Fix problem: System hang if load driver after running Audio manufacture test program.

Driver Version:

Windows 2000 ----- 1.14.01.00

Windows 98 ----- 1.14.01.00

Windows Millennium ----- 1.14.01.00

Windows 95 OSR2 ----- 1.14.01.00

Windows 95 ----- 1.14.01.00

Windows NT 4.0 ----- 1.14.01.00

Windows XP ----- 1.14.01.00

Windows for Workgroup ----- 1.14

Netware server 4.1x ----- 1.12

Netware server 4.2 ----- 1.12

Netware server 5.x ----- 1.12

Netware server 6.0 ----- 1.12



Netware client32 -----	1.12
Netware client -----	1.12
Packet driver -----	1.13
NDIS 2 for DOS -----	1.13
MS LAN Manager -----	1.13
NDIS 2 for OS/2 -----	1.13
DOS Diagnostic program -----	1.60
Windows 9x/2000 setup utility--	1.14
BootROM Rpl -----	1.11
PXE -----	1.08
PXERPL -----	1.08